Gotharman's Urano

Modular Synthesizer

Update Manual 8.77

Table of Contents

Bug Fixes

-Recording the CV inputs to Controller tracks did not work. Now it does.

Sample Xfade

Sometimes, when re-triggering monophonic samplings, a click would be heard.

These clicks can now be dampened or even be removed, by turning up the new Xfade parameter, found on the OSC SEL page.

Written by
Flemming Christensen
In 2024